



DATE: SEPTEMBER 28, 2009

ES&H ALERT #008

Incorrect Anchorage Connection

Within several areas of the project, it has been observed that some Self Retracting Lifelines (SRLs) are improperly connected to the anchorage point within the basket of an Aerial Work Platform (AWP). The SRLs should be connected with a carabineer directly to the anchorage point and the SRL. In some instances either the carabineer was only attached to the chain (only used to prevent theft) or not present at all.

All project personnel should inspect AWP's for the proper connection of fall protection equipment.

Incorrect anchorage connection



Correct anchorage connection

